EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	2226	(shear near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR .	ON	2007/09/18 12:41
L2	67	1 near8 wall.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/09/18 12:14
L3	21	2 and ((velocity speed accelerat\$5 position distance length) near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/09/18 12:31
L4	1103	wall and shear.ti.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/09/18 13:56
L5	74	4 and ((velocity speed accelerat\$5 position distance length) near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/09/18 12:26
L6	290	wall and shear and stress.ti.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/09/18 12:26
L7	34	6 and ((velocity speed accelerat\$5 position distance length) near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/09/18 12:29
L8	19	1 and active near3 (surface area plate sheet film coating substrate).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/09/18 12:31
L9	4	8 and ((velocity speed accelerat\$5 position distance length) near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/09/18 12:32

EAST Search History

L10	23	((shear near3 stress near3 wall) near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/09/18 12:43
L11 _.	428	(73/841-846).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/09/18 13:56
L12	0	11wall near3 shear.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/09/18 13:56
L13	. 4	11 and wall near3 shear.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/09/18 15:08
L14	8	(("4,464,928") or ("4,896,098") or ("5, 177,327") or ("5,961,080")).PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/09/18 15:10
L15	9	(("5,199,298") or ("6,341,532") or ("6,426,79")).PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR .	OFF	2007/09/18 15:12
L16		(("5,199,298") or ("6,341,532") or ("6, 426,796")).PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/09/18 15:12

9/18/07 3:58:37 PM C:\Documents and Settings\MNoori\My Documents\EAST\Workspaces\max.wsp